



OFFICE OF DEFECTS INVESTIGATION (ODI)

Recalls - Search Results

1 Record(s) Displayed.

Report Date : **October 27, 2008 at 04:08 PM**

NHTSA CAMPAIGN ID Number: **67V041000**

Vehicle Make / Model:

PONTIAC / FIREBIRD

Manufacturer: GENERAL MOTORS CORP.

NHTSA CAMPAIGN ID Number: 67V041000

Component: ELECTRICAL SYSTEM

Potential Number of Units Affected: 577

Summary:

Consequence:

Remedy:

Notes:

POSSIBILITY OF THE HEATER BLOWER MOTOR WIRE COMING INTO CONTACT WITH THE RIGHT HAND EXHAUST MANIFOLD WHICH, WHEN HOT, COULD MELT THE INSULATION. IF THIS SHOULD HAPPEN WHILE THE HEATER BLOWER IS OPERATING AT THE LOW SPEED SETTING, A RESISTOR IN THE CIRCUIT COULD OVERHEAT AND POSSIBLY CAUSE A FIRE UNDER THE INSTRUMENT PANEL. (REROUTE THE HEATER BLOWER LEAD-IN WIRING TO PREVENT IT FROM CONTACTING THE MANIFOLD.)