



OFFICE OF DEFECTS INVESTIGATION (ODI)

Recalls - Search Results

1 Record(s) Displayed.

Report Date : **October 27, 2008 at 04:11 PM**

NHTSA CAMPAIGN ID Number: **69V107000**

Vehicle Make / Model:

PONTIAC / FIREBIRD

Model Year(s):

1969

Manufacturer: GENERAL MOTORS CORP.

Mfr's Report Date: AUG 01, 1969

NHTSA CAMPAIGN ID Number: 69V107000

NHTSA Action Number: N/A

Component: SERVICE BRAKES, HYDRAULIC:FOUNDATION COMPONENTS:HOSES, LINES/PIPING, AND FITTINGS

Potential Number of Units Affected: 129

Summary:

Consequence:

Remedy:

Notes:

POSSIBILITY THAT INCORRECT LENGTH REAR FLEXIBLE BRAKE HOSE WAS INSTALLED. IF THIS CONDITION EXISTS, FULL COMPRESSION OF THE REAR SPRING MAY CONTACT AND CHAFE HOSE CAUSING LOSS OF BRAKE FLUID AND SUBSEQUENT LOSS OF BRAKES ON REAR WHEELS. (CORRECT BY INSTALLING PROPER LENGTH HOSE.)