



OFFICE OF DEFECTS INVESTIGATION (ODI)

Recalls - Search Results

1 Record(s) Displayed.

Report Date : **October 27, 2008 at 04:13 PM**

NHTSA CAMPAIGN ID Number: **69V148000**

Vehicle Make / Model:

PONTIAC / FIREBIRD

Model Year(s):

1969

Manufacturer: GENERAL MOTORS CORP.

Mfr's Report Date: OCT 13, 1969

NHTSA CAMPAIGN ID Number: 69V148000

NHTSA Action Number: N/A

Component: SERVICE BRAKES, HYDRAULIC:FOUNDATION COMPONENTS:HOSES, LINES/PIPING, AND FITTINGS

Potential Number of Units Affected: 86

Summary:

Consequence:

Remedy:

Notes:

POSSIBILITY THAT INCORRECT REAR BRAKE HOSE BRACKET WAS INSTALLED. IF THIS CONDITION EXISTS WITH FULL COMPRESSION ON REAR SPRING DURING OPERATION COULD CAUSE HOSE TO RUB AGAINST UNDERBODY AND WEAR HOLE IN HOSE AND RESULT IN LOSS OF BRAKE FLUID. (CORRECT BY INSTALLING CORRECT TYPE BRACKET.)